



K2 indicator, only weight scales with LCD display.



- LCD Display with automatic backlight.
- OIML-C3 loadcells.
- Auto Power Off Function.
- Tare function.
- Piece Counting function.
- Classification by weight (HI_OK_LO) function.
- Animals weighing function.
- Low battery indication.
- Internal rechargeable battery.



Technical characteristics

Modèle	K2
Reference	60018
Internal division	600.000
Display	LCD display with automatic backlight with 6 x 40 mm high digits
Weight units	kg, lb
Tare	100%
Connectivity (optional)	1 puerto RS-232
Structure material	ABS
External dimensions (mm)	240 x 180 x 105
Total net weight (kg)	1,380

Connectivity (optional)

Our indicator is available with the RS 232-C data output compatible with our printer or PC.



Available options

- Painted steel wall support
- PR3 Printer with cable
- Column support
- RS 232-C data output

Technical Specifications

Power: 220V

Battery: internal rechargeable 6V/4Ah

Operating temperature: -10°C / +40°C

External dimensions (mm)

